April 11, 1961 Spanish Fork, Utah

Mr. Donald C. Norseth Distribution Engineer State Engineer's Office State Capitol Salt Lake City 14, Utah

Dear Don:

Due to the past misunderstandings with the Spanish Fork City on their water rights, and because of the guess work in the measuring of the old Malcolm stream line because of the pumping system for Burt Isaac on the Malcolm line, I feel it would be better to have the Spanish Fork City install a second food or acre foot meter on their Malcolm stream line before going into their old City tank. If agreeable with you, please send Spanish Fork City a notice requesting them to install a proper meter before they receive any water through the Malcolm Stream line this irrigation season.

Also, please send Mr. Villiam D. Jackson of 254 South Escalante Dr. Spanish Fork, Utah, a letter requesting him to install a measuring weir either a V notch, or a dinolletti weir, or a Parshall Flume to properly measure his second foot of Decreed water through the Jackson est Ditch or formerly known as the West Simmons Ditch. The Calco measuring gate that is in the ditch now silts off and doesn't work properly. Please inform Mr. Jackson also that there will be a lock put on his gate in the future. At the time the locks was put on the Canyon Water Users gates the law suit of Mr. Jackson was pending, so the court would not allow the commissioner or deputy commissioner to put the lock on his gate at that time.

The secretary of the Spanish Fork City just called me on the telephone and ask if I had any information of the meeting called by the State Engineer's office for April 20, 1961 at 11 a.m. at the Armery Building in Spanish Fork. Please let me know on this meeting as I have no information about it.

Thank you.

Very truly yours

figured Mendenhall

from J. Mendenhall

stor Commissioner

Mater Commissioner